



LASER MEASURING TAPE

1901-5519-MK



TWO MEASUREMENT
MODES



QUICK
MEASUREMENTS



SELF LOCKING
MECHANISM



FOOT HOOK
(WITH MAGNET)




5.5m+40m

5.5M MEASURE TAPE



40M LASER RANGE



BASIC FUNCTION

In the Off State

Press and hold the button for 2 seconds to turn it on. 

Single Measurement

Short press the button to start a single measurement 

Continuous Measurement

Press and hold the button for 2 seconds to start continuous measurement 

Multi-function Measurement

Just press the button, you can switch distance, area, volume, and Pythagorean measurements. 



USB CHARGING



HOUSE OF TOOLS L.L.C
بيت العید والادوات (ش.ذ.م.)